

Restore factory default:



恢复出厂默认

Enable USB-COM interface:



USB 虚拟串口模式

Enable Code ID output:



允许添加 Code ID

Data end mark CRLF:



添加 CRLF 结束符 (0x0D 0x0A)